West Australian Rails

Number 10

Free photo e-mag of WA rail happenings during October 2013

Jim Bisdee publisher

email: pm1225@bigpond.com

Copyright Jim Bisdee © 2013



CBH014, CBH017 & CBH010 on 1K02 with ten wagons from Mawson derailment on Quairading line, Avon to Kwinana CBH terminal climbing grade through Hazelmere October 13th.

Photo Brendan Cherry

Following Mawson derailment on Quairading line and subsequent wagon recovery, services were suspended on this Tier3 line and was closed from October 31st owing to its poor condition. West Merredin Trayning line Tier3 line that had not seen any traffic since August then only to Nungarin CBH bin was also closed at same time owing to its poor condition. Services will remain on rest of the Tier3 lines till end of June 2014 while CBH and Brookfield Rail continue negotiations as to their long term future. SCT ran three CSR locomotives on 5MP9/1PM9 service to Forrestfield on October 13th the first time these units have run in WA. The final two SD70ACe units for FMG 720 and 721 arrived at Port Hedland October 27th. EMU set 096 arrived from builders in Old October 29th.



SCT CSR003, CSR004 & CSR009 on 1MP9 at Parkeston on October 12th on first run of a CSR loco in WA.



CSR003, CSR004 & CSR009 on 5MP9 at 628km on EGR at Bonnie Vale 12/10.



NR56 propels new EMU set 096 into old workshops Midland for bogie exchange 30/10. Photo Jim Bisdee



ALZ3208 withdrawn from service, stored exhaust covered at West Kalgoorlie 25/09.




LQ3121 runs AK car inspection train into Kalgoorlie loco to stable on its return from Leonora 12/10.



G&W 2210 stabled at Kalgoorlie loco 12/10 waiting to work AK cars back east.



CBH120 & CBH119 cross 6021, LDP006 & LDP002 shunting Aurizon intermodal terminal Forrestfield 29/10.



6021, LDP006 & LDP002 as #3 s/g shunter shunting out onto mainline 29/10.

Both photos Jim Bisdee



Q4001 & Q4011 on 1029 sulphur Kwinana to Malcolm at Thornlie October 29th. Photo Brendan Cherry



ACN4145 crossing P2506 & P2501 on empty ore in Narngulu yard October 14th.

Photo Phil Melling



CBH007 & CBH008 on empty grain to Mingenew just south Narngulu October 26th. Photo Phil Melling



LDP002 & LDP006 on 7AP1 Aurizon extra intermodal and SCT loading Millendon 28/10. Photo Simon Barber



LQ3121 on 5RC1 AK inspection cars Forrestfield to Kalgoorlie at Woodbridge 10/10.

Photo Jim Bisdee



DBZ2312 on 1238 empty caustic tankers at Mundijong October 20th.

Photo Brendan Cherry



P2508, P2509 & P2504 on 6476 empty woodchip wagon movement at Stratton 01/10. Photo Simon Barber



P2504, P2509 & P2508 on 3283 empty woodchip wagons to Avon at Swan View 01/10. Photo Simon Barber



EMU B series set 77 show special crossing A series set 12 at West Leederville 01/10. Photo Brendan Cherry



ACN4151 hauls empty Karara ore train away from Narngulu to Narngulu East 01/10.

Photo Phil Melling



New FMG SD70ACe 720 and 721 on transport floats Port Hedland wharf 27/10. Photo Toad Montgomery



P2511 & DAZ1901 on 5275 empty ballast Kwinana to Avon at Kenwick 17/10.

Photo Brendan Cherry





Q4013 on 2421 small ore cresting grade at 644km on EGR approaching Binduli 28/10. Photo Peter Donaghy



CBH010 on 6K72 last train to run on Tier3 Quairading line that ran light engine to Mawson to recover wagons from Mawson derailment then back to Avon at Mt Hardey October 11th.

Photo Sean McGarraghy



L3113 on 4438 empty nickel from Hampton at West Kalgoorlie October 23rd.



DAZ1901 hauls withdrawn AD1521 and AD1520 Forrestfield for storage, Hazelmere 01/10. Photo Jim Bisdee



LQ3121, DC2205 & LZ3103 on 5195 container train at Thornlie October 9th.

Photo Brendan Cherry



CBH013 & CBH016 about to enter CBH loop at Cranbrook to load October 23rd. Photo Daryle Phillips



DFZ2404, P2503 & P2507 on Mt Gibson ore at Bringo on October 12th.

Photo Phil Melling



P2502 & DFZ2401 on empty Mt Gibson ore cross ACN4149 & ACN4144 on loaded Karara mining ore at Grants crossing loop on Narngulu Mullewa line October 12th. Photo Phil Melling



NR56 on 4P31 empty EMU movement set 096 PFT to old workshops Midland 30/10.



9307 & 9302 on 1MP5 with inline fuel tankers and two crew cars South Guildford 30/10. Photo Simon Barber




S3308 & DBZ2313 on 1852 caustic tankers at Roelands October 20th.

Photo Brendan Cherry



LZ3108 & L3108 on #3 s/g shunter shunting intermodal terminal October 20th.

Photo Jim Bisdee



L3108 & LZ3109 on 1034 ore to Kwinana unloader at Welshpool October 20th.

Photo Jim Bisdee




LQ3121 on AK inspection cars at 7km on Esperance line October 14th.

Photo Peter Donaghy



Tunnel completed, Fremantle line and platform 11 removed at Perth Station October 13th. Photo Jim Bisdee



Platform 6 Perth Station being connected thru tunnel to Fremantle line and cut off platform 5 on 13/10.



Location of Perth carriage sheds, storage sidings, Fremantle line being redeveloped 13/10. Photos Jim Bisdee



L3115 stabled Kalgoorlie loco with replacement door believed ex 3102 October 5th. Photo Peter Donaghy



DAZ1901 on 4362 empty wagon movement West Merredin Avon near Bullaring 23/10.

Photo Jim Bisdee



DAZ1901 on 4362 crosses CBH001 loading at Wickepin CBH October 23rd.

Photo Jim Bisdee



CBH010 on empty grain crosses DAZ1901 in loop Yilliminning October 23rd.

Photo Jim Bisdee



LZ3107 & L3110 on 7478 nickel at dusk approaching Kalgoorlie October 12th.

Photo Peter Donaghy



CBH010 on empty grain crests grade at Yilliminning yard limit October 23rd.

Photo Jim Bisdee



AC4307 & Q4010 on 5416 empty ore rounding the curve at Binduli October 17th. Photo Peter Donaghy



DD2355 & DD2357 on 3542 light engine withdrawn locomotives Picton to Kwinana 22/10. Photo Jim Bisdee




S3306 on 3944 bauxite at Mundijong October 22nd.

Photo Jim Bisdee



DBZ2312 on 3237 caustic tankers approaching Mundijong October 22nd.

Photo Jim Bisdee



CBH 010 on 6K72 wagon recovery ex Mawson approaching York 11/10. Photo Sean McGarraghy END26/26